19. Discrepancy Indication Space

A

DHS 8022 A (1/88)

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name

Do Not Write Below This Line

Signature

EPA 8700-22 (Rev. 9-88) Previous editions are obsolete.

Yellow: TSDF SENDS THIS COPY TO GENERATOR WITHIN 30 DAYS

Day

Month

HAGIE MARILEO.	SEPAID NO.		- O D	OAD TO THE RESERVE OF	a - 100 to -	
	-6-5-1-0-0-0-5 9 Pcu	nifest ment No		of is not re	quired l	e shaded areas by Federal law.
A Generator's Name and Mailing Address raft Co. 19503 S. Normandie Avenue		A. State Manifest Document Number 89476963 B. State Generator's ID H.A. H. U. 3. 6. 0. 0. 5. 6. 9. 8 C. State Transporter's ID 013942				
Torrance, CA 90502 4. Generator's Phone (213) 533-6677 K. L. Anderson 722 M/S C6-10						
						5. Transporter 1 Company Name J.C.I. Environmental Services
7. Transporter 2 Company Name	8. US EPA ID Number		100 CH 100 CH 100 CH	te Transporter's ID		
Designated Facility Name and Site Address	10. US EPA ID Number	F. Transporter's Phone G. State Facility's ID				
USPCI Lone Mountain Facility						
U.S. Pollution Control, Inc. R/R 2, Box 180A	p.K.D.JOJ6J5J4J3J8J3J7J6		H. Facility's Phone (405)697-3237			
Waynoka, Okl. 73860		12. Cont	ainers	13. Total Quantity	14. Unit	l. Waste No.
11. US DOT Description (Including Proper Shipping Name, Hazi	ard Class, and ID Number)	No.	Туре	Quantity	Wt/Vol	State
Waste Sodium Hydroxide solution, (DOO2) (RQ 1,000 lbs.)	Corresive, UN1824					122 EPA/Other
(DOO2) (RQ 1,000 lbs.)		1 0 0	TIT	0 4 0 0 0	6	0002
b.						State
		11	1	1, 1, 1, 1		EPA/Other
C.						State
		1.1	1	1111		EPA/Other
d.						State
		1 1	١.	1 1 1 1		EPA/Other
J. Additional Descriptions for Materials Listed Above		1 1 -1	K. Ha	andling Codes for W	astes L	isted Above
Daco 4-L Aluminum Milling Solution, pH>12.5 Sodium Hydroxide 5-12% Sodium Aluminate 2-5% Sodium Suifide 2-4% Water = Remainder			c, d.			
wouldness and the second						
USPCI ID# LM89-0866-89 Okl. Was	te Plan # 96021					**************************************
	PROF	ILE #2 ER 145			<u> </u>	
15. Special Handling Instructions and Additional Information Guide # 60. Use proper protective clothing when handling. Return to MDC if rejected. TI-207 16. GENERATOR'S CERTIFICATION: I hereby declare that a and are classified, packed, marked, and labeled, and are national government regulations. If I am a large quantity generator, I certify that I have a proto be economically practicable and that I have selected the present and future threat to human health and the environ generation and select the best waste management metho	the contents of this consignment are in all respects in proper condition for ogram in place to reduce the volume practicable method of treatment, iment; OR, if I am a small quantity g d that is available to me and that I described to the content of the content	r fully and a pr transport storage, or enerator, I i	ccuratel by high	ste generated to the	e degre	e I have determined which minimizes the inimize my waste
15. Special Handling Instructions and Additional Information Guide # 60. Use proper protective clothing when handling. Return to MDC If rejected. T207 16. GENERATOR'S CERTIFICATION: I hereby declare that a and are classified, packed, marked, and labeled, and are national government regulations. If I am a large quantity generator, I certify that I have a protection to be economically practicable and that I have selected the present and future threat to human health and the environ generation and select the best waste management methologous printed/Typed Name	the contents of this consignment are in all respects in proper condition for ogram in place to reduce the volume practicable method of treatment, ment; OR, if I am a small quantity g d that is available to me and that I d	r fully and a pr transport storage, or enerator, I i	ccuratel by high	ste generated to the	e degre	e I have determined which minimizes the inimize my waste
15. Special Handling Instructions and Additional Information Guide \$ 60. Use proper protective clothing when handling. Return to MDC if rejected. TEVOT 16. GENERATOR'S CERTIFICATION: I hereby declare that a and are classified, packed, marked, and labeled, and are national government regulations. If I am a large quantity generator, I certify that I have a protection to be economically practicable and that I have selected the present and future threat to human health and the environ generation and select the best waste management methological.	the contents of this consignment are in all respects in proper condition for ogram in place to reduce the volume practicable method of treatment, ment; OR, if I am a small quantity g d that is available to me and that I d	r fully and a pr transport storage, or enerator, I i	ccuratel by high	ste generated to the	e degre	e I have determined which minimizes the nimize my waste Month Day Yes
15. Special Handling Instructions and Additional Information Guide # 60. Use proper protective clothing when handling. Return to MDC If rejected. TE-07 16. GENERATOR'S CERTIFICATION: I hereby declare that and are classified, packed, marked, and labeled, and are national government regulations. If I am a large quantity generator, I certify that I have a protect to be economically practicable and that I have selected the present and future threat to human health and the environ generation and select the best waste management metho Printed/Typed Name Kris L. Anderson Agent for N.D.A.	the contents of this consignment are in all respects in proper condition for ogram in place to reduce the volume practicable method of treatment, ment; OR, if I am a small quantity g d that is available to me and that I d	r fully and a pr transport storage, or enerator, I i	ccuratel by high	ste generated to the	e degre	e I have determined which minimizes the nimize my waste Month Day Yes
15. Special Handling Instructions and Additional Information Guide # 60. Use proper protective clothing when handling. Return to NOC if rejected. TE-07 16. GENERATOR'S CERTIFICATION: I hereby declare that a and are classified, packed, marked, and labeled, and are national government regulations. If I am a large quantity generator, I certify that I have a protection to be economically practicable and that I have selected the present and future threat to human health and the environ generation and select the best waste management metho Printed/Typed Name Kris L. Anderson Agent for N.D.A. 17. Transporter 1 Acknowledgement of Receipt of Materials	the contents of this consignment are in all respects in proper condition for ogram in place to reduce the volume practicable method of treatment, ment; OR, if I am a small quantity g d that is available to me and that I described to the small state of the smal	r fully and a pr transport storage, or enerator, I i	ccuratel by high	ste generated to the	e degre	e I have determined which minimizes the inimize my waste Month Day Yea O 3 1 4 9 0 Month Day Yea
15. Special Handling Instructions and Additional Information Guide 60. Use proper protective clothing when handeling. Return to NDC if rejected. TWO7 16. GENERATOR'S CERTIFICATION: I hereby declare that and are classified, packed, marked, and labeled, and are national government regulations. If I am a large quantity generator, I certify that I have a protect to be economically practicable and that I have selected the present and future threat to human health and the environgeneration and select the best waste management metho Printed/Typed Name Kris L. Anderson Agent for N.D.A. 17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name TOLO COCOC	the contents of this consignment are in all respects in proper condition for ogram in place to reduce the volume practicable method of treatment, ment; OR, if I am a small quantity g d that is available to me and that I described to the small state of the smal	r fully and a pr transport storage, or enerator, I i	ccuratel by high	ste generated to the	e degre	e I have determined which minimizes the inimize my waste Month Day Yea O 3 1 4 9 0 Month Day Yea
15. Special Handling Instructions and Additional Information Guide 60. Use proper protective clothing when handling. Return to MD II rejected. GENERATOR'S CERTIFICATION: I hereby declare that and are classified, packed, marked, and labeled, and are national government regulations. If I am a large quantity generator, I certify that I have a protobe economically practicable and that I have selected the present and future threat to human health and the environ generation and select the best waste management metho Printed/Typed Name Kris L. Anderson Agent for N.D.A. 17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name 18. Transporter 2 Acknowledgement of Receipt of Materials	the contents of this consignment are in all respects in proper condition for ogram in place to reduce the volume practicable method of treatment, ment; OR, if I am a small quantity g d that is available to me and that I consider the state of the state	r fully and a pr transport storage, or enerator, I i	ccuratel by high	ste generated to the	e degre	e I have determined which minimizes the inimize my waste Month Day Yea Q 3 1 4 9 0 Month Day Yea
15. Special Handling Instructions and Additional Information Guide 60. Use proper protective clothing when handeling. Return to NC if rejected. Theory 16. GENERATOR'S CERTIFICATION: I hereby declare that a and are classified, packed, marked, and labeled, and are national government regulations. If I am a large quantity generator, I certify that I have a protect to be economically practicable and that I have selected the present and future threat to human health and the environgeneration and select the best waste management metho Printed/Typed Name Kris L. Anderson Agent for N.D.A. 17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name 18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name 19. Discrepancy Indication Space	the contents of this consignment are in all respects in proper condition for ogram in place to reduce the volume peracticable method of treatment, iment; OR, if I am a small quantity g d that is available to me and that I consider the second of the secon	of fully and a por transport and toxicil storage, or enerator, I to can afford.	ccuratel by high ty of wa dispose have ma	ste generated to that currently available de a good faith effo	e degre	e I have determined which minimizes the inimize my waste Month Day Yea O 3 1 4 9 0 Month Day Yea
15. Special Handling Instructions and Additional Information Guide # 60. Use proper protective clothing when handeling. Return to MOLIT rejected. TE-07 16. GENERATOR'S CERTIFICATION: I hereby declare that and are classified, packed, marked, and labeled, and are national government regulations. If I am a large quantity generator, I certify that I have a proposent and future threat to human health and the environg generation and select the best waste management methon Printed/Typed Name Kris L. Anderson Agent for N.D.A. 17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name TOLU OGAE 18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name	the contents of this consignment are in all respects in proper condition for ogram in place to reduce the volume peracticable method of treatment, iment; OR, if I am a small quantity g d that is available to me and that I consider the second of the secon	of fully and a por transport and toxicil storage, or enerator, I to can afford.	ccuratel by high ty of wa dispose have ma	ste generated to that currently available de a good faith effo	e degre	e I have determined which minimizes the inimize my waste Month Day Yea O 3 1 4 9 0 Month Day Yea

DHS 8022 A (1/88)

89476963 USE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RP

EPA 8700—22 (Rev. 9-88) Previous editions are obsolete. Do Not Write Below This Line